

CSI Country Wide Case Study Safety Strategy Discussion

Construction Safety Investigator



Instructions

The objective of this tool is to provide field supervisors with information to proactively engage workers and discuss safety related concerns that they may encounter. Safety discussions should not be limited to the subject above and should pertain to the activities that workers will be involved in that may have the potential for safety related exposures..

Case Day:

June 8, 2005

Accident Type:

Fall Accident - Suspended Scaffold

Relevant laws, rules and codes may include:

1926.21(b)(2), 29 CFR 1926.451, .452, and .454

Case:

A 46 year-old male was fatally injured when he was pulled off of a roof and fell approximately 53 feet to the ground during building window operations..

Accident Detail:

The victim was located on the flat roof of a four story building, controlling a rolling roof outrigger. The victim was wearing a full-body safety harness with a retractable lanyard that was anchored to the rolling roof outrigger.

The victim's co-worker was suspended approximately five feet down the side of the building from the rolling roof outrigger.

As the victim was trying to reposition the rolling roof outrigger, it rolled to the edge of the roof and then rolled off of the roof, dragging the victim over the roof. The victim, co-worker and the rolling outrigger all fell to the ground below with the rolling roof outrigger landing on top of the co-worker.

Reconstructive Safety Evaluation:

- What are some of the possible causes of the accident being discussed?
- What actions could have been taken that might have prevented this accident from occurring?

