

# CSI Country Wide Case Study Safety Strategy Discussion

## Construction Safety Investigator

CHUBB®

### Instructions

---

The objective of this tool is to provide field supervisors with information to proactively engage workers and discuss safety related concerns that they may encounter. Safety discussions should not be limited to the subject above and should pertain to the activities that workers will be involved in that may have the potential for safety related exposures.

### Case Day:

June 2009

### Accident Type:

Fall Accident - Skylight

### Relevant laws, rules and codes may include:

29CFR 1926.20(a)(1), 1926.21(b)(2), 1926.501(a)(2), 1926.501(b)(4)(i), (ii) and (iii), 1926.502, 1926.503, Skylight Mfr's installation and safety instructions

### Case:

---

A 28 year-old construction worker was severely injured when he fell through a roof on which he was working.

### Accident Detail:

---

The worker was employed by a roofing contractor who at the time was in the process of installing fiberglass skylights.

At the time of the incident, the worker had installed a skylight unit and was completing the unit's installation. At some point during the installation, the worker allegedly leaned onto the skylight dome, which broke under the worker's weight, and he fell through the skylight to the floor below.

Emergency services responded and airlifted the injured worker to the hospital.

### Reconstructive Safety Evaluation:

---

- What are some of the possible causes of the accident being discussed?
- What actions could have been taken that might have prevented this accident from occurring?

