

# CSI Country Wide Case Study Safety Strategy Discussion

## Construction Safety Investigator

CHUBB®

### Instructions

---

The objective of this tool is to provide field supervisors with information to proactively engage workers and discuss safety related concerns that they may encounter. Safety discussions should not be limited to the subject above and should pertain to the activities that workers will be involved in that may have the potential for safety related exposures.

### Case Day:

April 2008

### Accident Type:

Fall Accident - From Bridge

### Relevant laws, rules and codes may include:

29CFR 1926.20(a)(1), 1926.21(b)(2), 1926.501, 1926.502, 1926.503

### Case:

---

A construction worker on a bridge was killed when he fell 120 feet.

### Accident Detail:

---

The worker was part of a bridge painting crew, which at the time, was preparing the bridge for a new paint job. The crew was working within a protective shroud where they would remove the old paint along with other environmental contamination in preparation for the new paint.

To prevent them from falling while in the protective shroud and within the confines of the working platform, the workers must “tie-off,” using their personal fall arrest systems to the provided lifelines and anchorage points.

It is unclear why the worker was not tied off, but when he attempted to maneuver from one location within the bridge supports to another, he lost his balance and fell. Since he was not tied off, he fell through the bridge supports and approximately 120 feet to the ground below.

### Reconstructive Safety Evaluation:

---

- What are some of the possible causes of the accident being discussed?
- What actions could have been taken that might have prevented this accident from occurring?

